

Ride Information		Comments
<b>YEAR</b>	1986	
<b>MAKE</b>	Lincoln	
<b>MODEL</b>	Mark VII LSC	
<b>MILEAGE</b>	65,842	
<b>TRANSMISSION</b>	Automatic	
<b>VIN NUMBER</b>	1LNBP98M0GY699833	
<b>INTERIOR</b>	Desert Tan Cloth & Leather	
<b>INTERIOR COLOR</b>	Tan	<i>Interior looks and smells brand new!</i>
<b>BODY COLOR</b>	Marron Clearcoat Metallic	
<b>ENGINE</b>	8 Cylinder	
<b>DRIVE TYPE</b>	Rear Wheel Drive	
<b>FUEL TYPE</b>	Gas	

Road Test	Result	Comments
Engine Starting Easily	✓ Pass	<i>Engine started easily once battery jumper attached</i>
Engine running well after Started	✓ Pass	<i>Engine idled nicely after cold start</i>
Transmission performance	✓ Pass	
Differential Performance	✓ Pass	
Wheel Bearing Performance	✓ Pass	
Braking Performance	✓ Pass	
Suspension Performance	✓ Pass	
Steering Performance	✓ Pass	
Alignment	✓ Pass	

Mechanical	Result	Comments
Air Filter	✓ Pass	
Battery Condition	✓ Pass	
Charging System	⚠ Caution	<i>Battery was dead from lack of use</i>
Engine Cooling Fan	✓ Pass	
Hoses & Clamps	✓ Pass	
Radiator	✓ Pass	
Engine Coolant Condition	✓ Pass	
Coolant Leaks	✓ Pass	
Belts	✓ Pass	
Power Steering System	✓ Pass	
Power Steering Fluid Condition	✓ Pass	
Engine Oil Condition	✓ Pass	
Engine Oil Leaks	✓ Pass	
Transmission Fluid Condition	✓ Pass	
Transmission Fluid Leaks	✓ Pass	
Brake System Condition	✓ Pass	
Brake Fluid Leaks	✓ Pass	
Emergency Brake	✓ Pass	
Differential/Transaxle Leaks	✓ Pass	
Exhaust System	⚠ Caution	<i>Heat shield rattled slightly exhaust fully warmed up</i>
CV Boots and Joints	✓ Pass	
Shocks & Bushings	✓ Pass	<i>Air suspension sits at correct ride height despite lack of use</i>
Ball Joints & Tie Rods	✓ Pass	
Radiator Cap	✓ Pass	

Interior	Result	Comments
Steering Wheel	✓ Pass	
Horn	✓ Pass	
Cruise Control	✓ Pass	
Seat Condition	✓ Pass	
Seat Belts	✓ Pass	
Clock	✓ Pass	
Radio/Navigation/Media	✓ Pass	
Door Cards	✓ Pass	
Power Locks	✓ Pass	
Power Windows	⚠ Caution	Passenger side window sticks when raised - needs someone to guide it up
Center Console	✓ Pass	
Dashboard	✓ Pass	
Dashboard Lights	✓ Pass	
Air Conditioning	✗ Fail	All equipment in place but compressor would not kick on - further diagnosis required
Heater	✓ Pass	
Carpet	✓ Pass	
Floor Mats	✓ Pass	Two sets of front mats are included as part of sale
Signs of Smoking?	✓ Pass	
Headliner	✓ Pass	
Blower Motor	✓ Pass	
Instruments	✓ Pass	
Window Function	⚠ Caution	Passenger side window sticks when raised - needs someone to guide it up
Interior Trim	✓ Pass	
Sunroof	✓ Pass	
Sun Visors	✓ Pass	
Any Unusual Orders?	✓ Pass	

Tires	Size	Manufacturer	Tread Depth	Condition	Notes
Driver's Side Front	215/65R15	Accelerera Eco Plush	✓ Pass	✓ Pass	"0121" Date Code Noted
Driver's Side Rear	215/65R15	Accelerera Eco Plush	✓ Pass	✓ Pass	"0121" Date Code Noted
Passenger Side Front	215/65R15	Accelerera Eco Plush	✓ Pass	✓ Pass	"0121" Date Code Noted
Passenger Side Rear	215/65R15	Accelerera Eco Plush	✓ Pass	✓ Pass	"0121" Date Code Noted

Wheels	Size	Manufacturer	Lug Nuts	Condition	Notes
Driver's Side Front	15	OEM	✓ Pass	✓ Pass	Factory Wheel Lock Installed
Driver's Side Rear	15	OEM	✓ Pass	✓ Pass	Factory Wheel Lock Installed
Passenger Side Front	15	OEM	✓ Pass	✓ Pass	Factory Wheel Lock Installed
Passenger Side Rear	15	OEM	✓ Pass	✓ Pass	Factory Wheel Lock Installed
Spare Tire	15	OEM	✓ Pass	✓ Pass	Factory Wheel Lock Installed

Exterior	Result	Comments
Windshield Wipers	⚠ Caution	We recommend replacement
Windshield Washer	✓ Pass	
Body Panel Alignment	✓ Pass	
Scratches	✓ Pass	
Paint Condition	✓ Pass	
Seals	✓ Pass	
Rust	✓ Pass	
Exterior Lights	✓ Pass	
Power Door Mirrors	✓ Pass	
Bumpers	✓ Pass	
Side Moldings	✓ Pass	
Convertible Top	N/A	
Underbody / Frame Condition	✓ Pass	
Glass	✓ Pass	
Floors	✓ Pass	
Rocker Panels	✓ Pass	
Body Filler Evidence	✓ Pass	
Hood	✓ Pass	
Doors	✓ Pass	
Trunk Lid / Hatch	✓ Pass	
Dings	✓ Pass	
Dents	✓ Pass	

#### Summary

My first impression of this 1986 Lincoln Mark VII is that it is a nice survivor quality car that has been garage kept most of its life. The car needed a jump start when I arrived to perform the inspection and photography.

The car started almost immediately with a jump pack. I was not with the car long enough to confirm whether it needs a new battery.

The interior looks and smells like new. While the passenger side window motor pulled the window down slowly, it struggled to raise the glass without someone helping guide, so further troubleshooting will be needed to repair it. The Air conditioning compressor did not engage, so further troubleshooting will be needed to determine whether it just needs a charge from lack of use or is some other repair needed.

The car's undercarriage presents very nicely with no signs of rust.

The car drove well with no odd noises or smells. Noteworthy is the fact I did not hear any squeaks or rattles during the test drive.

Given the local weather during the inspection and photography, the car appears dirty. A thorough exterior detail and wax is all this car needs to