

Ride Information	
YEAR	2000
MAKE	Porsche
MODEL	Boxster
MILEAGE	58,634
TRANSMISSION	Automatic
VIN NUMBER	WP0CA2980YU623413
INTERIOR	Leather
INTERIOR COLOR	Light Tan
BODY COLOR	Arena Red
ENGINE	6 Cylinder Flat Six
DRIVE TYPE	Rear Wheel Drive
FUEL TYPE	Gas

Road Test	Result	Comments
Engine Starting Easily	✓ Pass	
Engine running well after Started	✓ Pass	
Transmission performance	✓ Pass	
Differential Performance	✓ Pass	
Wheel Bearing Performance	✓ Pass	
Braking Performance	✓ Pass	
Suspension Performance	✓ Pass	
Steering Performance	✓ Pass	
Alignment	✓ Pass	

Exterior	Result	Comments
Windshield Wipers	✓ Pass	
Windshield Washer	✓ Pass	
Body Panel Alignment	✓ Pass	
Scratches	⚠ Caution	See pictures provided
Paint Condition	✓ Pass	
Seals	✓ Pass	
Rust	✓ Pass	
Exterior Lights	✓ Pass	
Power Door Mirrors	✓ Pass	
Bumpers	✓ Pass	
Side Moldings	✓ Pass	
Convertible Top	⚠ Caution	Wear Consistent With Age
Underbody / Frame Condition	✓ Pass	
Glass	✓ Pass	
Floors	✓ Pass	
Rocker Panels	✓ Pass	
Body Filler Evidence	✓ Pass	
Hood	✓ Pass	
Doors	✓ Pass	
Trunk Lid / Hatch	✓ Pass	
Dings	⚠ Caution	See Pictures Provided
Dents	✓ Pass	

Interior	Result	Comments
Steering Wheel	✓ Pass	
Horn	✓ Pass	
Cruise Control	✓ Pass	
Seat Condition	✓ Pass	
Seat Belts	✓ Pass	
Clock	✓ Pass	
Radio/Navigation/Media	✓ Pass	
Door Cards	✓ Pass	
Power Locks	✓ Pass	
Power Windows	✓ Pass	
Center Console	✓ Pass	
Dashboard	✓ Pass	
Dashboard Lights	✓ Pass	
Air Conditioning	✓ Pass	
Heater	✓ Pass	
Carpet	✓ Pass	
Floor Mats	✓ Pass	
Signs of Smoking?	✓ Pass	
Headliner	✓ Pass	
Blower Motor	✓ Pass	
Instruments	✓ Pass	
Window Function	✓ Pass	
Interior Trim	✓ Pass	
Sunroof	✓ Pass	
Sun Visors	✓ Pass	
Any Unusual Orders?	✓ Pass	

Mechanical	Result	Comments
Air Filter	✓ Pass	
Battery Condition	✓ Pass	Brand New Battery
Charging System	✓ Pass	
Engine Cooling Fan	✓ Pass	
Hoses & Clamps	✓ Pass	
Radiator	✓ Pass	
Engine Coolant Condition	✓ Pass	
Coolant Leaks	✓ Pass	
Belts	✓ Pass	
Power Steering System	✓ Pass	
Power Steering Fluid Condition	✓ Pass	
Engine Oil Condition	✓ Pass	
Engine Oil Leaks	✗ Fail	Non-dripping leak appears to be from main seal
Transmission Fluid Condition	✓ Pass	
Transmission Fluid Leaks	✓ Pass	
Brake System Condition	✓ Pass	
Brake Fluid Leaks	✓ Pass	
Emergency Brake	✓ Pass	
Differential/Transaxle Leaks	✓ Pass	
Exhaust System	✓ Pass	
CV Boots and Joints	✓ Pass	
Shocks & Bushings	✓ Pass	
Ball Joints & Tie Rods	✓ Pass	
Radiator Cap	✓ Pass	

Tires	Size	Manufacturer	Tread Depth	Condition	Notes
Driver's Side Front	225/40R18	Michelin	✓ Pass	✓ Pass	
Driver's Side Rear	225/40R18	Michelin	✓ Pass	✓ Pass	
Pasenger Side Front	225/40R18	Michelin	✓ Pass	✓ Pass	
Passenger Side Rear	225/40R18	Michelin	✓ Pass	✓ Pass	

Wheels	Size	Manufacturer	Lug Nuts	Condition	Notes
Driver's Side Front	18	Porsche	✓ Pass	✓ Pass	Optional Porsche Design Wheel
Driver's Side Rear	18	Porsche	✓ Pass	✓ Pass	Optional Porsche Design Wheel
Pasenger Side Front	18	Porsche	✓ Pass	✓ Pass	Optional Porsche Design Wheel
Pasenger Side Rear	18	Porsche	✓ Pass	✓ Pass	Optional Porsche Design Wheel
Spare Tire	18	Porsche	✓ Pass	✓ Pass	Doughnut Spare

Summary

Overall, this 2000 Porsche Boxster Base is a very clean, low-mileage example. The seller just replaced the battery.

The oil pan shows evidence of slow oil seepage. The seller indicates its a very slow leak that does not make it onto a floor, which could indicate the need for a rear main seal replacement. While attending to the rear main seal, we recommend the buyer also consider upgrading the intermediate shaft bearing ("IMS") bearing at the same time.