

Ride Information	
<b>YEAR</b>	1990
<b>MAKE</b>	Ford
<b>MODEL</b>	Thunderbird Super Coupe
<b>MILEAGE</b>	63,850
<b>TRANSMISSION</b>	Ford 4-Spped Automatic Overdrive ("AOD")
<b>VIN NUMBER</b>	1FAPP64RXLH154393
<b>INTERIOR</b>	Cloth & Leather
<b>INTERIOR COLOR</b>	Black & Gray
<b>BODY COLOR</b>	Black
<b>ENGINE</b>	210 HP 3.8L Supercharged V6
<b>DRIVE TYPE</b>	Rear Wheel Drive
<b>FUEL TYPE</b>	Gas

Road Test	Result	Comments
Engine Starting Easily	✓ Pass	
Engine running well after Started	✓ Pass	
Transmission performance	✓ Pass	
Differential Performance	✓ Pass	
Wheel Bearing Performance	✓ Pass	
Braking Performance	✓ Pass	
Suspension Performance	✓ Pass	
Steering Performance	✓ Pass	
Alignment	✓ Pass	

Exterior	Result	Comments
Windshield Wipers	✓ Pass	
Windshield Washer	✓ Pass	
Body Panel Alignment	✓ Pass	
Scratches	✓ Pass	
Paint Condition	⚠ Caution	Scratches & Chips consistent with mileage & age
Seals	✓ Pass	
Rust	✓ Pass	
Exterior Lights	✓ Pass	
Power Door Mirrors	✓ Pass	
Bumpers	✓ Pass	
Side Moldings	✓ Pass	
Convertible Top	<b>N/A</b>	
Underbody / Frame Condition	✓ Pass	
Glass	⚠ Caution	Rear Window Moulding Worn (See Pictures)
Floors	✓ Pass	
Rocker Panels	✓ Pass	
Body Filler Evidence	✓ Pass	
Hood	✓ Pass	
Doors	✓ Pass	
Trunk Lid / Hatch	✓ Pass	
Dings	✓ Pass	
Dents	✓ Pass	

<b>Interior</b>	<b>Result</b>	<b>Comments</b>
Steering Wheel	✓ Pass	
Horn	✓ Pass	
Cruise Control	✓ Pass	
Seat Condition	⚠ Caution	Driver's side bolster minor wear (see pics)
Seat Belts	✓ Pass	
Clock	✓ Pass	
Radio/Navigation/Media	✓ Pass	Aftermarket Radio - Factory Unit Included
Door Cards	✓ Pass	
Power Locks	✓ Pass	
Power Windows	✓ Pass	
Center Console	✓ Pass	
Dashboard	✓ Pass	
Dashboard Lights	✓ Pass	
Air Conditioning	✓ Pass	Converted professionally to R134A
Heater	✓ Pass	
Carpet	✓ Pass	
Floor Mats	✓ Pass	Includes Unused set of 35th Anniversary Mats
Signs of Smoking?	✓ Pass	
Headliner	✓ Pass	
Blower Motor	✓ Pass	
Instruments	✓ Pass	
Window Function	✓ Pass	
Interior Trim	✓ Pass	
Sunroof	✓ Pass	
Sun Visors	✓ Pass	
Any Unusual Orders?	✓ Pass	

<b>Mechanical</b>	<b>Result</b>	<b>Comments</b>
Air Filter	✓ Pass	
Battery Condition	✓ Pass	
Charging System	✓ Pass	
Engine Cooling Fan	✓ Pass	
Hoses & Clamps	✓ Pass	
Radiator	✓ Pass	
Engine Coolant Condition	✓ Pass	
Coolant Leaks	✓ Pass	
Belts	✓ Pass	
Power Steering System	✓ Pass	
Power Steering Fluid Condition	✓ Pass	
Engine Oil Condition	✓ Pass	
Engine Oil Leaks	✓ Pass	
Transmission Fluid Condition	✓ Pass	
Transmission Fluid Leaks	✓ Pass	
Brake System Condition	✓ Pass	
Brake Fluid Leaks	✓ Pass	
Emergency Brake	✓ Pass	
Differential/Transaxle Leaks	✓ Pass	
Exhaust System	✓ Pass	
CV Boots and Joints	✓ Pass	
Shocks & Bushings	✓ Pass	
Ball Joints & Tie Rods	✓ Pass	
Radiator Cap	✓ Pass	

Tires	Size	Manufacturer	Tread Depth	Condition	Notes
Driver's Side Front	16"	Kumho	✓ Pass	✓ Pass	
Driver's Side Rear	16"	Kumho	✓ Pass	✓ Pass	
Pasenger Side Front	16"	Kumho	✓ Pass	✓ Pass	
Passenger Side Rear	16"	Kumho	✓ Pass	✓ Pass	

Wheels	Size	Manufacturer	Lug Nuts	Condition	Notes
Driver's Side Front	16"	Ford	✓ Pass	⚠ Caution	Some paint fade noted
Driver's Side Rear	16"	Ford	✓ Pass	✓ Pass	
Pasenger Side Front	16"	Ford	✓ Pass	✓ Pass	
Pasenger Side Rear	16"	Ford	✓ Pass	✓ Pass	
Spare Tire	16"	Ford	✓ Pass	✓ Pass	

**Summary**

*As the video depicts, this 1990 Ford Thunderbird SC 35th Annicversary Edition is a nicely maintained and detailed survivor. Every option on the car worked as designed during my inspection. During the ride-along, the car tracked straight, did not have any noises or squeats, and proved to have plenty of power. The ambient air temperature was very humid and in the low 80's during the test, and this Thunderbird's converted A/C system provided plenty of cold air.*